
## FITTING INSTRUCTIONS 1/2

	]		FITTING INSTRUCTIONS 1/2
CAR	MINI Countryman/Paceman R60/R61 Cooper S All4	PART NO.	SMN026C
YEAR	2010-2016	FIT KITS	414FK
NOTES	Will also fit JCW Models Use O.E clamp to fix Scorpion front pipe to O.E.	FEATURES	Pipe diameter:- 63.5mm/2.5"




NO.	PART NO.	DESCRIPTION	QTY	DATE	06/04/2023	
1	560BM	Front Pipe	1	ISSUE	00	
2	561BM	Primary Link Pipe	1	AUTHORISED	S Shipley	
3	562BM	Secondary Link Pipe	1			
4	881BM	Rear Silencer	1			
5	882BM	Trim Bend	2			
6	Z023.10055	100mm Black Daytona Trim	2			
7	567BM	Mounting Bracket (see page 2 for fitting)	1			
Fit Kit	·					
8	Z016.10064	65mm H/D Clamp	7	<ul> <li>Fitting instructions overleaf</li> </ul>		
	Z016.10035	Bobbin	1			
	Z017.10064	M8 Spring Washer (Use one each side of the bobbin, this gose on after item 4)	2			
	Z017.10831	M8 Washer (Use one each side of the bobbin, this gose on before item 3)	2			
	Z017.11209	M12 Washer	2			
	Z017.10121	5/16" Nut	2			
	Z017.10160	M12 x 40mm Bolt (Push the bolt thru from exhaust side, from left to right)	1			
	Z017.10183	M12 Nyloc Nut	1			

NOTE: ENSURE SCORPION SYSTEM IS CLEAR OF MOVING PARTS AND ALL ORIGINAL FUNCTIONS WORK CORRECTLY.



CAR	MINI Countryman/Paceman R60/R61 Cooper S All4	PART NO.	SMN026C
YEAR	2010-2016	FIT KITS	414FK
NOTES	Will also fit JCW Models Use O.E clamp to fix Scorpion front pipe to O.E.	FEATURES	Pipe diameter:- 63.5mm/2.5"



NO.	PART NO.	DESCRIPTION	QTY	
Fit Kit	Fit Kit			
1	567BM	Mounting Bracket	1	
Following items to be used from Fitting Kit 090FK				
2	Z016.10035	Bobbin	1	
3	Z017.10064	M8 Spring Washer (Use one each side of the bobbin, this gose on after item 4)	2	
4	Z017.10831	M8 Washer (Use one each side of the bobbin, this gose on before item 3)	2	
5	Z017.11209	M12 Washer	2	
6	Z017.10121	5/16" Nut	2	
7	Z017.10160	M12 x 40mm Bolt (Push the bolt thru from exhaust side, from left to right)	1	
8	Z017.10183	M12 Nyloc Nut	1	

DATE	06/04/2023
ISSUE	00
AUTHORISED	S Shipley

Assemble supplied rubber mounting and fixings to differential mounting point as shown in the photograph above.

NOTE: ENSURE SCORPION SYSTEM IS CLEAR OF MOVING PARTS AND ALL ORIGINAL FUNCTIONS WORK CORRECTLY.



I